Navajo Abandoned Uranium Mine

Site Screen Report

This form is for use at the site of abandoned uranium mines (AUM) located on Navajo Nation lands. Applicable sites include all mine and mine features that have or have not undergone reclamation by the Navajo Abandoned Mine Lands Reclamation Program, including features, adits, pits and waste piles. Applicable sites also include all AUM sites listed in the USEPA CERCLIS database, all sites listed in the 2008 AUM GIS Report issued by USACOE and USEPA, all AUM sites on allotment lands associated with the Navajo Nation, and any and all AUM sites not listed in any database located on Navajo lands. Reconnaissance of any sites located on lands adjacent to Navajo lands that may be impacting Navajo lands will need to be coordinated with the authorities appropriate to those lands.

The purpose of the form is to ascertain the status and location of the identified AUM site, and record all immediate site information associated with the mine site. Decisions and recommendations on what additional steps are needed will be provided on a separate document.

Mine Name: Etsitty No. 1

Mine ID: **85**

Navajo AUM Central Region

Prepared by:

Weston Solutions, Inc.

Contract: W91238-06-F-0083

20074.063.017.0020

August 2011

Part I	Site Identification, Location and Status				
Site Names and ID numbers as applicable					
Mine ID:	85				
Map ID:	C15				
CERCLIS:	NNN0009091	86			
Navajo Abandoned Mine Land Reclamation Program: NA-0703					
Local name / Aliases: Etsitty #1; M.O. 5					
Chapter and local area: Black Mesa					
County: Apa	che	State: Arizon	a		
Lat/Long:	36.286811860	9 N / -109.848	275852 W		
Nearby road	and highway:	Route 29	Local Post Office:	Blue Gap, AZ	
Surface Land Status: check one or more and provide ownership and contact information below					
Tribal Trust ? Private Bureau of La State			Public lands Tribal Fee Land Allotment Fee land		
Subsurface Mineral Rights:					
No information on subsurface mineral rights ownership was found in the EPA/AUM Database					
Claim and operator information:					

The mine surface land status is classified as Tribal Trust Land. Historical documents identified the operator of the mine as Sayan, Nelson & Glabraith from 1954 to 1956. No additional historical ownership / lease information was identified in the EPA / AUM database.

Number of residential structures within 200 feet of mine: None

Part II Summary of Radiological Readings

Mine ID: 85

Highest gamma radiation measurement: 99,548 counts per minute (cpm)


Background Average: 16,082 cpm **Two Times Background:** 32,164 cpm

Describe any other radiological measurements:

A total of 3,974 gamma radiation measurements were collected from the mine site, ranging from 9,498 cpm to 99,548 cpm. Measurements collected in the vicinity of the waste rock were found at a maximum level of approximately 100,000 cpm. The measurements are represented in Figures 1 and 2.

Distribution Chart and Statistics:

Site Gamma Radiation Statistics			
Number of Readings	3,974		
Minimum (cpm)	9,498		
Maximum (cpm)	99,548		
Mean (cpm)	25,356		
Median (cpm)	20,253		
Standard Deviation	14,177		



Part III Status of Reclamation and Mine Waste

Mine ID: 85

Program (NAMLRP) Point Features Database:

NAMLRP Status of the mine site: Reclaimed: Yes Waste Pile onsite: Yes

NAMLRP Project Number: NA-0703

NAMLRP Mine features: 2 Portals

The following information was obtained from field observations collected during the 2011 site screening:

Provide description and status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all caps.

Observed reclamation work and status:

Adits:

None observed

Waste Piles:

Waste rock piles onsite

Pits:

None observed

Shafts:

None observed

Other Debris and Mine Features:

Erosion control features atop mine site

Part IV Site Observations and Environs

Observed Structures (number and human habitation status of structures at the following distances from the mine site):

0 to 200 feet: None observed

200 feet to 0.25 mile: None observed

Observed Public or Commercial Structures (schools, clinics, Chapter Houses, places of business and any other structures used by members of the community at the following distances from the mine site):

0 to 200 feet: None observed

200 feet to 0.25 mile: Abandoned sheep pen and wood structure 350 ft NW of site

Levels measured around the perimeter(s) of the identified structure(s):

Background Levels

Observed Water Sources (number and type of wells and surface water sources that are potentially used for human consumption at the following distances from the mine site):

0 to 0.25 miles: None observed

0.25 miles to 4 miles: None observed

Sensitive Environments (all sensitive environments located within visible range of the mine site, including: wetlands, endangered species, habitats and approximate locations of sites that may be under protection of the government of the Navajo Nation):

None observed

Known Site History (information from interviews with Chapter officials and residents and database review, includes: mine ownership, type of mining operation, period of operation, known amount of production, and any other information provided):

The Etsitty No. 1 mine claim consists of an area of 21,665.34 m². The mine was identified as being operational from 1954 to 1956. While operational, the mine had a total reported production volume of 129 tons. The mine surface land status is classified as Tribal Trust Land. Historical documents identified the operator of the mine as Sayan, Nelson & Glabraith from 1954 to 1956. No additional historical ownership / lease information was identified in the EPA / AUM database.

Part V Response Action Summary

Summary of Evaluation Factors:

Accessibility:

Was the mine easily accessible to potential human activity? Yes

Radiological Measurements:

Were any gamma radiation measurements collected at the mine greater than two times the site-specific background levels?

Yes

Waste Piles:

Were any unreclaimed waste piles observed at the mine with gamma radiation measurements greater than two times the site-specific background levels? Yes

Structures:

Were any structures observed within 200 feet of the mine? No

Potential Drinking Water Sources:

Were any potential drinking water sources observed within 4 miles of the mine? No

Reclamation:

Was the mine reported to be previously reclaimed, or did the mine appear to be reclaimed?

Yes

Part VI Photos



Photo 1: Mine Site #85



Photo 2: Mine Site #85; Northern waste pile



Photo 3: Mine Site #85; Southern waste pile



Photo 4: Mine Site #85; Erosion control features



Photo 5: Mine Site #85; Wood structures



Photo 6: Mine Site #85; Wood structure / corral



Photo 7: Mine Site #85; Top of mine



Photo 8: Mine Site #85; Sign



Photo 9: Mine Site #85; Sign



Photo 10: Mine Site #85

Part VII Contacts Reports and Information

Name:	Eugene Esplain		
Title or official role (if any):	Navajo EPA Superfund Program		
Telephone number:	(928) 871-7331		
Address:	PO Box 2946, Window Rock, AZ 86515		
Information provided:	Lead Regulatory Agency		
Name:	Francis John		
Name.	Francis John		
Title or official role (if any):	Local resident		
Telephone number:	(928)-675-0205		
Information provided:	Provided information about mine history, road access, and reclamation		
	access, and reclamation		
Name:			
Title or official role (if any):			
Telephone number:			
Address:			
Information provided:			

Figure 1 - Gamma Radiation Measurements, Above Two Times Background
Etsitty No. 1 (85)
Black Mesa Chapter, Navajo Nation






Figure 2 - Gamma Radiation Measurements Etsitty No. 1 (85) Black Mesa Chapter, Navajo Nation



Gamma Radiation Measurements

- 0 10,000 cpm
- 10,000 25,000 cpm
- 25,000 50,000 cpm
- 50,000 100,000 cpm
- 100,000 250,000 cpm
- 250,000 500,000 cpm
- 500,000 1,000,000 cpm



Observed Reclamation Feature

Observed Waste Pile

Observed Structure

/////// Steep Grade







Feet



Measured as counts per minute (cpm)

Average background 16,082 cpm